

GREGORY S. BELL Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program May 19, 2010

	DATES
Reviewed:	11/1/

Mine Name: Silver Dream	Permit Number: S/027/0084					
Operator Name: Steele, Robert	Inspection Date: 05/12/2010					
Inspector(s): Brett Gregory for John Rogers	Time: 3:00 pm					
Other Participants: None	Mine Status: Active					
Elements of Inspection	Evaluated Comment Enforcement					
1. Permits, Revisions, Transfer, Bonds						
2. Public Safety (shafts, adits, trash, signs, highwalls)						
3. Protection of Drainages / Erosion Control						

2.	Public Safety (shafts, adits, trash, signs, highwalls)				
3.	Protection of Drainages / Erosion Control		A **		
4.	Deleterious Material				
5.	Roads (maintenance, surfacing, dust control, safety)				
6.	Concurrent Reclamation				
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)				
8.	Water Impoundments				
9.	Soils				
10.	Revegetation				
11.	Air Quality				
12.	Other	\bowtie	\bowtie		

Permit fee: Current Bond Amount: \$0

<u>Purpose of Inspection</u>: This was a routine inspection.

Inspection Summary:

The mining claims are located in a wilderness study area. No recent mining activity or disturbance was observed.

Evaluated comments:

- 1) In order to have a valid mining permit, regulation R647-3-111.1.11 requires the operator furnish and maintain a reclamation surety. The bond amount determined by the Division for the Silver Dream mine is \$20,600 dollars. The amount is based from the number of acres requested in the mining Notice of Intention to Commence Small Mining Operations (Plan) submitted by the operator. If the bond amount seems egregious, then the operator should amend the NOI to reflect the acres of disturbance desired.
- 12) A GPS map has been made showing access to the site.

(Photographs attached)



Inspection Date: 05/12/2010

Page 2 of 3 S/027/0084

Conclusions and Recommendations:

The operator needs to post and maintain adequate reclamation surety with the Division of Oil, Gas and Mining (DOGM) in the amount of \$20,600 dollars. Failure to provide adequate reclamation surety will result in the withdrawal of the mining permit.

Inspector's Signature


BG; jr, pbb, vs

cc: Robert Steele, Operator Jerry_Mansfield@blm.gov


Enclosure: GPS map







Location of claim-1.



Two claim markers. (One of the posts is barely visible in the background!)

